

7th May 2024

Our insurers are supporting us with the required works. The first step is to ensure that the building which is concrete floors has been dried out. No work to restore flooring can take place until the building has had chance to dry. We have removed flooring and are using dehumidifiers to speed this process.

